



- NOTES:
1. CLEAN AND PRIME MEMBRANE IN LAP AREAS WITH JM TAPE PRIMER/WASH.
 2. FOR BALLASTED OR MECHANICALLY FASTENED SYSTEMS, FIELD MEMBRANE MUST BE REINFORCED.

DRAWING NO. EB-18T	BASE FLASHING WITH SEPARATE JM EPDM SHEET AS FLASHING AND JM EPDM ANCHOR DISCS TO DECK - TAPE			
	SCALE N.T.S.	ISSUE DATE 3-06	CAD SP18BFD	