


NOTE:
 CLEAN AND PRIME MEMBRANE IN LAP AREAS WITH JM TAPE PRIMER/WASH. THE JM TAPE PRIMER/WASH MUST BE COMPLETELY DRY AND TACK FREE BEFORE LAP CEMENT APPLICATION.

| | | | | |
|----------------------------|--|--------------------|----------------|---|
| DRAWING NO. EB-1 | BASE FLASHING WITH JM EPDM MEMBRANE AS FLASHING AND ANCHOR DISCS TO WALL - ADHESIVE | | |  |
| | SCALE N.T.S. | ISSUE DATE 3-06 | CAD SP01BFW | |