


NOTE:
 CLEAN AND PRIME MEMBRANE IN LAP AREAS WITH JM TAPE PRIMER/WASH. THE JM TAPE PRIMER/WASH MUST BE COMPLETELY DRY AND TACK FREE BEFORE LAP CEMENT APPLICATION.

DRAWING NO. EB-1	BASE FLASHING WITH JM EPDM MEMBRANE AS FLASHING AND ANCHOR DISCS TO WALL - ADHESIVE			
	SCALE N.T.S.	ISSUE DATE 3-06	CAD SP01BFW	