


NOTES:

1. FOR BALLASTED OR MECHANICALLY FASTENED SYSTEMS, FIELD MEMBRANE MUST BE REINFORCED.
2. THE JM TAPE PRIMER/WASH MUST BE COMPLETELY DRY AND TACK FREE BEFORE LAP CEMENT APPLICATION.

DRAWING NO. EB-14	BASE FLASHING WITH SEPARATE JM EPDM SHEET AS FLASHING AND JM EPDM ANCHOR DISCS TO WALL - ADHESIVE			 Johns Manville
	SCALE N.T.S.	ISSUE DATE 3-06	CAD SP14BFW	